



EXHAUST FAN OUTAGE.

Location: GILLESPIE RESEARCH.

Disruption/Outage: LAB/FUME HOOD

Date: SATURDAY, 04/05/2025.

Duration: 0500-1700, APPROX 12HRS.

Details: THE MOTOR ON EXHAUST FAN #1 NEEDS TO BE REPLACED. THIS WILL REDUCE THE EXHAUST FLOW DURING THE OUTAGE.

We appreciate your cooperation and apologize for any inconvenience this may cause. If you have any questions or concerns, please contact Facilities Tony Garrit, at 949-824-5140 or tgarrit@uci.edu

Cc: Building Facility Manager (please route to appropriate MSO/affected faculty and/or staff)

DATE POSTED:
PLEASE POST UNTIL: